

[illegible]

Page 1

**Accept**

[illegible]**Setup Start**

**Stop**

1. The first step is to identify the problem. This involves understanding the current situation and what needs to be changed.

2. The second step is to set goals. These should be specific, measurable, achievable, relevant, and time-bound.

3. The third step is to develop a plan. This involves identifying the resources needed and the steps to be taken.

4. The fourth step is to implement the plan. This involves putting the plan into action and monitoring progress.

5. The fifth step is to evaluate the results. This involves comparing the actual results with the goals and identifying areas for improvement.

6. The sixth step is to adjust the plan. This involves making changes to the plan based on the evaluation results.

7. The seventh step is to communicate the results. This involves sharing the results with the relevant stakeholders.

8. The eighth step is to document the process. This involves recording the steps taken and the results achieved.

9. The ninth step is to review the process. This involves reflecting on the process and identifying lessons learned.

10. The tenth step is to improve the process. This involves making changes to the process based on the lessons learned.

**Cust Item ID:**

Year	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100
1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	

**Customer:**

Run Start




Date: 11/02/25 Tooling:

Date:

**Date:** \_\_\_\_\_ **SPC (Y/N):** \_\_\_\_\_

Date:

**Stop**

100		PURCHASING	0.00		<u>CL</u> <u>11/02/25</u> <u>(50)</u>
	Purchasing	<b>Memo</b>	0.00		
	Purchasing	Issue P/O: <u>13559</u> <input type="checkbox"/> Bearing as per Dwg D3121 <input type="checkbox"/> Possible Supplier: SKF P/N: 61900-2Z or KML P/N: 6900-ZZ <input type="checkbox"/> Material release note is required			
110		Receive & Inspect for Damage & Mat'l Certs	0.00		<u>Pu/4/28</u> <u>(50)</u>
	Packaging	<b>Memo</b>	0.00		
	Packaging	Ensure Material Release Note is attached			
120		QC6- Inspect dimensions to drawing	0.00		<u>Coenter</u> <u>(ASD)</u>
	QC	<b>Memo</b>	0.00	<u>Su/02/28</u>	
	Quality Control	Inspect diimensions as per Dwg D3121 and attached certification Dwg Rev <u>E</u>			

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

**Work Order ID 66734**

Friday, February 25, 2011 9:57:45 AM



Page 2

Item ID: D3121-23

Accept



Setup Start



Revision ID:

Stop



Item Name: Bearing

Start Date: 2/25/2011 Start Qty: 50.00



Cust Item ID:

Required Date: 2/28/2011 Req'd Qty: 50.00



Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

130

Identify as per dwg &amp; Stock Location

0.00



Packaging

Memo

235  
G-A 18x  
w/o 66163

0.00

Packaging

→ 11/02/28

11/02/28

SD

140

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

11/03/01

CL 11/03/01

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

# Picklist Print

Friday, February 25, 2011 9:57:41 AM

Page 1

Work Order ID: 66734



Parent Item: D3121-23



Parent Item Name: Bearing


Start Date: 2/25/2011

Required Date: 2/28/2011

Start Qty: 50.00

Required Qty: 50.00

Comments: IPP A: 04.02.19 New Issue KJ/DS  
IPP Rev:B ECN 1060 07-11-12 DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
6900ZZ  Bearing		Purchased		No		100	Each	0.0000	1	50			



*164/28 (50)*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_


Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


**NOTE:** Date & initial all entries

**DART**


DESIGN #	DRAWN BY LE	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED #	APPROVED #	DRAWING NO. D3121	REV. E SHEET 10 OF 10
DATE 07.11.07	TITLE BRACKET ASSEMBLY		SCALE 1:1

**D3121-17 WASHER (SCALE 2:1)**


- 1) REPLACES PREMIER P/N B32-23001-17
- 2) MATERIAL: AISI 303 SS ROUND BAR, ANNEALED (REF DART SPEC. M303R)
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL SHARP EDGES 0.005 TO 0.015

**D3121-19 BEARING (SCALE 1:1)**


- 1) POSSIBLE SUPPLIER: KING BEARING P/N 6000-2ZJ/EM FAFNIR P/N 9100KDD
- 2) ALL DIMENSIONS ARE IN INCHES

**D3121-23 BEARING (SCALE 1:1)**


- 1) POSSIBLE SUPPLIER: SKF P/N 61900-2Z OR KML P/N 6900-ZZ
- 2) ALL DIMENSIONS ARE IN INCHES

**D3121-21 BOLT (SCALE 1:1)**

- 1) MATERIAL: AISI 303 SS HEX, ANNEALED (REF DART SPEC. M303H0.500)
- 2) FINISH: NONE
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL SHARP EDGES 0.005 TO 0.015

**D3121-25 CAP (SCALE 1:1)**

- 1) MATERIAL: DELRIN ROD,  $\phi 1.25$  (REF DART SPEC. M-DELRIN-R1.250)
- 2) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 3) ALL DIMENSIONS ARE IN INCHES

**D3121-241 BEARING ASSEMBLY (SCALE 1:1)**

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



Dart Aerospace Ltd.  
1270 Aberdeen Street  
Hawkesbury, ON K6A 1K7  
Tel: 613 632 9577  
Fax: 613 632 1053

## PURCHASE ORDER

Purchase Order ID PO13559

Purchase Order Date 2/25/2011

PO Print Date 2/25/2011

Page Number 1 of 1

Order From : VC-MAI001

MAIN INDUSTRIAL SALES LTD.  
1475, TESSIER  
HAWKESBURY, ON K6A 3S6  
CA

Contact Name		Buyer	Chantal Lavoie
Vendor Phone	613 632 3595	Requisition Nbr	
Vendor Fax	613 632 0262	Tax Resale Nbr	10127-2607
Vendor Account Nbr		Terms	Net 30
		Currency	CAD
		FOB	Destination-Collect

Ship To : DART AEROSPACE LTD 1270 ABERDEEN  
HAWKESBURY, ON K6A 1K7  
CANADA

PAID  
CZ 11/10/25

Line Nbr	Reference Revision ID Vendor Part Number	Description/ Mfg ID	Req Date/ Taxable	Req Qty/ Unit of Measure	Ship Method	Unit Price	Extended Price
1	6900ZZ	Bearing	2/28/2011 Yes	50.00 Each	Yours ppd	\$1.6200	\$81.00

Special Inst: AS PER DWG D3121 REV. E  
B66734  
SKF P/N: 61900-2Z OR KML P/N: 6900-ZZ

PO Total: \$81.00

CERTIFICATE OF CONFORMITY  
REQ'D UPON DELIVERY

Change Nbr: 1

Change Date: 2/25/2011

No substitution or deviation without  
consent.  
Certificate of Conformity or Material  
Certification required when applicable



